

OUT57742

TOP SECRET 142339Z

1966 FEB 14 23 55Z

25X1

1

SUBJECT: MISSION 4024 ANOMALIES

15 FEB 1966

1. THE MCD REQUIRES THE FOLLOWING CORRECTIONS.

A. REV. 41 THE ROLL VALUES FOR THE FOLLOWING S/I FRAMES 23 THRU 42 INCLUSIVE SHOULD BE 11.340 DEG. RATHER THAN 24.110 DEG. AS LISTED IN THE MCD.

B. REV. 32 FRAME 1 CHANGE ROLL TO -2.1 DEG. CHANGE MODE TO 2F CHANGE CRAB TO 2.5 DEG. ALL INFO COMPUTED FROM PREVIOUS PARAMETERS WILL BE INCORRECT. STELLAR INDEX OPERATIONS ON REV. 32 FRAMES 1, 2, AND 3 CHANGE ROLL ANGLE TO -2.1 DEG. ALL OTHER INFO CORRECT.

1. THE FOLLOWING MISSION ANOMALIES OCCURRED.

A. THE MIRROR DRIVE MACHANISM DID NOT OPERATE PROPERLY FROM THE END OF FRAME 2 REV. 25 THRU THE END OF FRAME 19 REV. 26 THE PITCH VALUES FOR THE MIRROR DURING THIS TIME IS IN ERROR.

B. CORRELATION OF MCD AND FRAME TITLING INFORMATION ON REV. 55 AND REV. 62.

MCD TITLING INFO.

REV	FRAME	REV	FRAME
55	1	55A	1
55	2	55A	2
55	3	55D	1

Declassification Review by NGA/DoD

DISTRIBUTION 2		
Cy No.	Office	Action
1	File	
2	OS	
	ADMIN	
	SEC BR	
	P & DS	
	CSD	
	SPD	
	PD	
	FSD	
	PSD-ICB	
3,4,5	TID	
	IAD	
	PA3	
	DIAXX-4	
	SPAD	
	NSA-LO	
	DIA-AP	

Advance copy
Sanitized

TOP SECRET

25X1

-2-

55	4	55D	2
55	5	55D	3
55	6	55D	4
55	7	55D	5
55	8	55D	6
55	9	55D	7
55	10	55D	8
55	11	55D	9
55	12	55D	10
55	13	55D	11
55	14	55D	12
55	15	55D	13
55	16	55D	14
62	--	62	1
62	1	62	2
62	2	62	3

T O P S E C R E T

--END OF MESSAGE--

1